



Attorney Docket No. 392.1864

CofC
\$

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Yoshiharu INABA, et al.

Application No.: 10/765,908

ATTENTION

Confirmation No.: 2609

CERTIFICATE OF CORRECTION

Filed: January 29, 2004

BRANCH

U.S. Patent No.: 6,855,904

Issued: February 15, 2005

Certificate

JUL 25 2005

For: WIRE ELECTRIC DISCHARGE MACHINING APPARATUS

of Correction

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Sir:

Patentees respectfully request that a Certificate of Correction be issued in the subject patent, pursuant to 35 USC § 254 and 37 CFR § 1.322, to correct the errors shown on the attached Form PTO-1050. A check in the amount of \$100 to cover the cost of the Certificate is attached.

One or more of the errors shown on the attached Form PTO-1050 is or are within the responsibility of the undersigned; each thereof is of a clerical or typographical nature or of minor character and occurred in good faith, and the correction thereof is consistent with the prosecution record.

Respectfully submitted,

STAAS & HALSEY LLP

07/21/2005 SSITHIB1 00000057 6855904

01 FC:1811

100.00 DP

Date:

July 20, 2005

By:

H. J. Staas
Registration No. 22,010

1201 New York Ave, N.W., Suite 700
Washington, D.C. 20005
Telephone: (202) 434-1500
Facsimile: (202) 434-1501

JUL 26 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : 6,855,904

DATED : February 15, 2005

INVENTOR(S) : Yoshiharu INABA, et al.

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

(73) Assignee
should be in caps --FANUC--

(30) Foreign Patent Documents
change "JP 4-42420" to --JP5-42420--

Col. 2, line 39, change "diagram" to --diagrams--

Col. 2, line 46, remove ",,"

Col. 3, line 10, delete "paragraph return" after "in"

Col. 4, line 55, change "S" to --5--

Col. 4, line 66, change "S" to --5--

MAILING ADDRESS OF SENDER:
STAAS & HALSEY
1201 New York Avenue, N.W.
Suite 700
Washington, DC 20005

PATENT NO. 6,855,904

No. of add'l copies
@ 304 per page

→
JUL 26 2005